

CONSUMER
PROTECTION



WISCONSIN
DEPARTMENT OF
AGRICULTURE,
TRADE AND
CONSUMER
PROTECTION

OFFICE LOCATION

2811 Agriculture Drive
Madison, WI 53708-8911

1-800-422-7128
608-224-4960

News

February 2014

Edition

Dear Wisconsin Children's Safety Advocates:

In January 2014, the U.S. Consumer Product Safety Commission issued a total of **12 recalls relating to products affecting children**. Attached is a summary of the releases identifying the product, the problem, and what should be done with the recalled product.

We have found that not all of the recalls are picked up by the news media as they occur. This monthly summary will give you the opportunity to review all of the children's product safety recalls for the past month. If you are interested in a complete text of the recall, double click on the hyperlink at the end of the recall description. This will direct you to the recall notice located on the CPSC website.

- Under Armour Recalls Infant Sports Jersey Kits Due To Laceration and Choking Hazards ([14-709](#))
- Norwood Furniture Recalls Science Tables due to Injury Hazard ([14-706](#))
- SRAM Recalls Hydraulic Bicycle Brakes Due to Crash and Injury Hazards ([14-079](#))
- Playtex Recalls Pacifier Holder Clips Due to Choking Hazard ([14-084](#))
- Baby Rattles Recalled by Midwest-CBK Due to Choking Hazard ([14-083](#))
- Nationwide Industries Recalls Trident Pool Gate Latches Due To Failure to Secure Hazardous Areas ([14-085](#))
- Strollers Recalled by Britax Due to Partial Fingertip Amputation Hazard ([14-098](#))
- Fred & Friends Recalls Infant Pacifiers Due to Choking Hazard ([14-097](#))
- West Marine Recalls Folding Bicycles; Frames Can Break Causing Riders to Fall ([14-096](#))
- IKEA Expands Recall of Junior Beds that Pose Laceration Hazard ([14-094](#))
- Reebok-CCM Recalls Senior Hockey Elbow Pads Due to Risk of Elbow Injury ([14-093](#))
- Horizon Hobby Recalls Remote Controlled Model Helicopters Due to Injury Hazard ([14-091](#))

If you would like to sign up for the Keep Your Kids Safe newsletter, please subscribe at

https://public.govdelivery.com/accounts/WIDATCP/subscriber/new?topic_id=WIDATCP_161 or contact Bobbi Erb at (608) 224-4955 or bobbi.erb@wisconsin.gov.

If you have any questions or want to file a complaint regarding an unsafe product, contact:

Wisconsin Department of Agriculture, Trade and Consumer Protection
Bureau of Consumer Protection
2811 Agriculture Drive
Madison, WI 53708

KEEP YOUR KIDS SAFE

Release Number: (#14-709) Under Armour, Inc., of Baltimore, M.D., is announcing the voluntary recall of about 62 Tottenham Hotspur Infant Home Kits. The infant home kit consists of a white jersey and navy blue shorts and socks in sizes 0, 6 months, 12 months and 18 months. The jersey has style #1238534 printed on a side seam label. The jerseys are white with navy blue trim and navy blue UA and Tottenham Hotspur logos. The navy blue shorts have white trim and white UA and Tottenham Hotspur logos. The socks are navy blue.

Problem: The shoulder snaps on the jersey can detach, posing laceration and choking hazards.

What to do: Consumers should immediately take the recalled home kits away from children and return the kits to the retailer where purchased or contact Under Armour for a full refund. You can contact Under Armour toll-free at (888) 823-0343 from 8 a.m. through 6 p.m. ET Monday through Friday or online at www.underarmour.com and click on Recall for more information.



<http://www.cpsc.gov/en/Recalls/Recall-Alerts/2014/Under-Armour-Recalls-Infant-Sports-Jersey-Kits/>

Release Number: (#14-706) School Outfitters of Norwood, O.H., has announced the voluntary recall of about 655 Norwood Furniture's science tables. The rectangular tables have a black laminate finish tabletop with a light brown hardwood base and four legs. There are black floor grips at the bottom of each wooden leg. The table has two rectangular, front open compartments. The affected products include item numbers, NOR-PIH1027-SO for the 24" W x 48" L x 30" H table, NOR-PIH1028-SO for the 24" W x 54" L x 30" H table and NOR-PIH1029-SO for the 24" W x 60" L x 30" H table.

Consumers can locate the item number on the underside of the tabletop which is listed with the Commercial Furniture phone number, the OCI# and Country of Origin: China.

Problem: The wooden legs can split causing instability which poses an injury hazard to those using the table.

What to do: Customers should contact School Outfitters to set up repair appointments with installation experts to replace the legs on all affected tables free of charge. School Outfitters is contacting customers directly. You can contact School Outfitters toll-free at (866) 619-1776 Monday through Friday from 8:00 a.m. to 8:00 p.m. ET or online at www.schooloutfitters.com and click on Email Customer Service for additional information.



<http://www.cpsc.gov/en/Recalls/Recall-Alerts/2014/Norwood-Furniture-Recalls-Science-Tables/>

Release Number: (#14-079) SRAM, LLC, of Chicago, I.L., announces the voluntary recalls about 25,350 bicycle brake models include SB Red Hydraulic Road Disc, SB Red Hydraulic Road Rim, SB 700 Hydraulic Road Disc and SB 700 Hydraulic Road Rim, used as either front or rear brakes. The SB RED brake lever is labeled "RED" on the body of the lever assembly. The SB 700 brake lever is labeled "S-Series" on the body of the lever assembly. The serial numbers for the recalled brakes have the digit "3" as the fourth digit of the serial number. The serial number can be found on the bottom of the caliper body. The brakes were sold as aftermarket products and as original equipment on the bicycles.

Problem: The brake systems can fail, posing a crash and injury hazard.

What to do: Consumers should immediately stop using bicycles equipped with the recalled SRAM brake systems and contact any SRAM dealer to arrange for a free replacement product to be installed and to receive a \$200 product

voucher or cash per customer. You can contact SRAM at (800) 346-2928 between 9 a.m. and 5 p.m. Monday through Friday CT or visit the firm's website at www.sram.com and click on Recall Information for more information.



<http://www.cpsc.gov/en/Recalls/2014/SRAM-Recalls-Hydraulic-Bicycle-Brakes/>

Release Number: (#14-084) Playtex Products Inc., of Dover, D.E., announces the voluntary recall of about 1.25 million in the U.S. and 150,000 in Canada Playtex pacifier holder clips that attach a pacifier to items like clothing, diaper bags and strollers. It is a plastic clip with a figure and a "Playtex" copyright logo that slides up and down to adjust the clip, a ribbon and a clear plastic ring that stretches to fit the pacifier. The pacifier holder was sold in green with a monkey figure, pink with a flower and blue with a tow truck.

Problem: The pacifier holder clips can crack and a small part can break off which poses a choking hazard to small children.

What to do: Consumers should immediately take the recalled pacifier holders away from infants and contact Playtex for instructions on how to return the product for a full refund. You can contact Playtex toll-free at (888) 220-2075 from 8 a.m. to 6 p.m. ET Monday through Friday or online at www.playtexproducts.com and click on Recall for more information.



<http://www.cpsc.gov/en/Recalls/2014/Playtex-Recalls-Pacifier-Holder-Clips/>

Release Number: (#14-083) Midwest-CBK LLC, of Cannon Falls, M.N., is announcing the voluntary recall of about 1,900 donut-shaped polyester knit fabric baby rattles with heads and arms to resemble a bear, monkey and a lion. They measure about 7 inches in diameter by 2 inches thick. Sweet-ums and Midwest-CBK are printed on a hang tag on the rattles. A label sewn into the rattles has Midwest-CBK, the production date 04/2013 and the batch #:00001281 printed on it.

Problem: The head on the rattle can detach, posing a choking hazard to young children.

What to do: Consumers should take the recalled rattles away from young children immediately and contact Midwest-CBK for a full refund. You can contact Midwest-CBK at (800) 394-4225 from 8 a.m. to 5 p.m. CT Monday through Friday or online at www.mwcbk.com and click on Product Recall Information.



<http://www.cpsc.gov/en/Recalls/2014/Baby-Rattles-Recalled-by-Midwest-CBK/>

Release Number: (#14-085) Nationwide Industries, Inc., of Tampa, F.L., is announcing the voluntary recall of about 2,500 magnetic gate latches are 10" or 20" models in black or white. They are marked with the "Trident" name and image on the face of the latch body below the key hole. The latch body, which is typically attached to a fence post, contains a knob and a key cylinder on the uppermost portion and a recessed area on the bottom portion designed to engage and retain the striker. The striker, which contains the magnet, is typically attached to the active gate portion of a fence gate assembly, and moves with the gate as it is opened and closed. The Trident Latches are frequently used to secure gates for pools. **Problem:** The magnet contained in the striker portion of the latch assembly can come loose, preventing the latch from securing a gate.

What to do: Consumers should contact Nationwide Industries for a replacement striker kit that can be installed with a Phillips head screwdriver. You can contact Nationwide

Industries at (800) 409-3901 from 8:00 a.m. to 4:30 pm ET Monday through Friday, or use afterhours voicemail, via e-mail at Striker@NationwideIndustries.com, or online at www.nationwideindustries.com and click on "Info on Trident Striker replacements" for more information.



<http://www.cpsc.gov/en/Recalls/2014/Nationwide-Industries-Recalls-Trident-Pool-Gate-Latches/>

Release Number: (#14-098) Britax Child Safety Inc., of Fort Mill, S.C., announces the voluntary recall of about 216,000 in the United States and 8,800 in Canada Britax B-Agile, B-Agile Double and BOB Motion strollers. The single and double strollers were sold in various color schemes, including black, red, kiwi, sandstone, navy and orange. They were manufactured between March 2011 and June 2013 and have the following model numbers: U341763, U341764, U341782 and U341783 for the B-Agile strollers; U361818 or U361819 for the B-Agile Double strollers; and U391820, U391821 and U391822 for the BOB Motion strollers. The model number and the manufacture date in YYYY/MM/DD format can be found on label located on the inside of the stroller's metal frame near the right rear wheel.

Problem: The hinge on the stroller's folding mechanism can partially amputate consumers' fingertips, break their fingers or cause severe lacerations, among other injuries, when they press the release button while pulling on the release strap.

What to do: Consumers should stop using the recalled strollers immediately and contact Britax to receive a free repair kit. You can contact Britax; toll-free at (866) 204-1665 from 8:30 a.m. to 6:00 p.m. ET Monday through Thursday and

8:30 a.m. to 5:00 p.m. Friday, visit the company's websites at www.britaxusa.com or www.bobgear.com and click on "Safety Notice" at the top right corner or on "Learn More" at the bottom center of the page, or e-mail strollerrecall@britax.com for more information.



<http://www.cpsc.gov/en/Recalls/2014/Strollers-Recalled-by-Britax/>

Release Number: (#14-097) Fred & Friends, of Cumberland, R.I., a division of Lifetime Brands, Inc., of Garden City, N.Y., announces the voluntary recall of about 183,000 in the United States and 17,000 in Canada, Fred & Friends Chill Baby pacifiers, including the Artiste with a black plastic beard and mustache, Volume with a black volume control knob and Panic with a red panic button. The pacifier's name and UPC are printed on the packaging. The Artiste's UPC is 728987021282, the Volume style's UPC is 728987020599 and the Panic style's UPC is 728987020605. The pacifiers are plastic and silicone rubber and measure about 2 inches wide and 1½ inches tall.

Problem: The pacifiers fail to meet federal safety standards. The beard on the Artiste and the knob on the Volume pacifiers can detach, posing a choking hazard to young children. In addition, the ventilation holes on the Volume and Panic pacifier guards are too small.

What to do: Consumers should immediately take the recalled pacifiers away from young children and return them to Fred & Friends for a \$12 refund. Fred & Friends is providing a postage paid envelope for consumers to return the recalled pacifiers. You can contact Fred & Friends toll-free at (855) 346-6372 from 8 a.m. to 5 p.m. ET Monday through Friday, email the firm at pacifiersconsumer@fredandfriends.com or online at www.fredandfriends.com and click on Pacifier Recall for more information.



<http://www.cpsc.gov/en/Recalls/2014/Fred-and-Friends-Recalls-Infant-Pacifiers/>

Release Number: (#14-096) West Marine Products Inc., of Watsonville, C.A., announces the voluntary recall of about 4,600 folding bicycles, the Jetty Express 2 and the Port Runner 2, that are designed for use in and around docks and marinas. The Jetty Express 2 has a blue and white frame and folds at a hinge in the middle. Jetty Express 2 is printed on the bike's frame. The Port Runner 2 has a red frame and folds at a hinge in the middle. Port Runner 2 is printed on the bike's frame.

Problem: The bicycle's frame can break during use, posing a fall hazard to the rider.

What to do: Consumers should immediately stop using the recalled bicycles and return them to West Marine for a free replacement folding bicycle. You can contact West Marine at (800) 262-8464 between 8 a.m. and 5 p.m. PT Monday through Friday, or online at www.westmarine.com and click on Product Recalls at the bottom of the page for additional information.



<http://www.cpsc.gov/en/Recalls/2014/West-Marine-Recalls-Folding-Bicycles/>

Release Number: (#14-094) IKEA North America Services LLC, of Conshohocken, P.A., is announcing the voluntary recall of about 3,500 IKEA junior beds include the KRITTER and SNIGLAR models with a guard rail on one side. The pine wood KRITTER beds have animal cut-outs, such as a dog and cat on the headboard. A label on the headboard or underside of the

KRITTER bed has a date stamp of 1114 to 1322 representing the year and week of production (YYWW), a 600.904.70 model number, and 19740 supplier number. The SNIGLAR natural beech wood beds have a white painted fiberboard insert on the headboard and footboard of the bed. A label on the headboard or underside of the SNIGLAR bed has a date stamp of 1114 to 1318 (YYWW), a 500.871.66 model number, and 18157 supplier number. This recall expands the date stamp for SNIGLAR beds to 1049 to 1318. The beds measure about 65 inches long by 30 inches wide with a 22 to 26 inch high headboard.

Problem: The metal rod connecting the guard rail to the bed frame can break in use, posing a laceration hazard.

What to do: Consumers should immediately stop using the recalled KRITTER and SNIGLAR junior beds and contact IKEA to receive a free repair kit. You can contact IKEA toll-free at (888) 966-4532 anytime or online at www.ikea-usa.com and click on the recall link on the top of the page for more information.



<http://www.cpsc.gov/en/Recalls/2014/Baby-Rattles-Recalled-by-Midwest-CBK/>

Release Number: (#14-093) Reebok-CCM Hockey Inc. of Montpelier, V.T., is announcing the voluntary recall of about 2,100 in the United States and 1,600 in Canada, Reebok EP20K Senior (SR) Hockey Elbow Pads with, all-foam elbow caps. The pads are white with grey and black colored fabric. The word Reebok appears on the upper and lower arm sections of each elbow pad, and the words 20K PRO appears on the forearm of each pad. There are three Velcro brand closure bands on each elbow pad. The product code K101SR EP20K is located on the inside label of each elbow pad and on the outside of the polybag in which some products were packaged. The elbow pad comes in S, M, L and XL.

Problem: The molded foam padding inside the elbow pads can become cracked, fractured or split, which poses a risk of injury to the elbow.

What to do: Consumers should immediately stop using the recalled elbow pads and return the product to place of purchase for a full refund

or replacement, or return the product directly to Reebok- CCM Hockey Inc. for a replacement. You can contact CCM Hockey, Inc. at (800) 451-4600 in the U.S. from 9 a.m. to 5 p.m. ET., Monday through Friday, online at <http://reebokccm.com> and then click on button marked "Recall," or by email at returns@reebokccm.com.



<http://www.cpsc.gov/en/Recalls/2014/Reebok-CCM-Recalls-Senior-Hockey-Elbow-Pads/>

Product Recalls listed under "Legal" at the bottom of the page for more information.



<http://www.cpsc.gov/en/Recalls/2014/Horizon-Hobby-Recalls-Remote-Controlled-Model-Helicopters/>

Release Number: (#14-091) Horizon Hobby Inc., of Champaign, I.L., is announcing the voluntary recall of about 1980 in the U.S. and 200 in Canada Blade 500 X BNF and Blade 500 3D BNF and RTF Remote Controlled Model Helicopters with model numbers BLH 1800, BLH 1800M1, BLH 1850, and BLH 4080. The helicopters are about 33.5 inches long and 11.8 inches tall and weigh about 4 lbs. The canopy of the 500 X has the "500 X" logo on each side. The canopy of the 500 3D has the "500 3D" logo on each side. The tail rotor grip for each model is a black plastic holder that holds the tail rotor blades of the helicopter in place. The grips are approximately 1 ¼ inches tall and ½ inch wide.

Problem: The tail rotor grip used for securing the tail rotor blade to the tail rotor hub can separate and release from the helicopter, posing a risk of a crash and injury hazard. The head on the rattle can detach, posing a choking hazard to young children.

What to do: Consumers should immediately stop using the recalled radio-controlled helicopters and contact Horizon Hobby for a replacement tail grip and instructions for installation. You can contact Horizon Hobby toll-free at (877) 504-0233 from 8 a.m. to 7 p.m. CT Monday through Friday, 8 a.m. to 5 p.m. CT Saturday, and noon to 5 p.m. CT Sunday, or online at www.horizonhobby.com, and click on